



Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Exhaust Lambda Bank

0.80 0.969LA 1.30

Values

exhaustcamshaft

Data

Cursor

Time 14:04.096

Outing Time 14:04.096

Distance

Outing Distance

Time/Distance Graph

Exhaust Camshaft Bank 1 Position 20.3 °RTD

Exhaust Camshaft Bank 2 Position 20.0 °RTD

Exhaust Camshaft Bank 1 Control Error -0.7 °RTD

Exhaust Camshaft Bank 2 Control Error -0.4 °RTD

Inlet Camshaft Bank 1 Position 31.1 °ADV

Inlet Camshaft Bank 2 Position 30.4 °ADV

Engine Speed 2726 rpm

Exhaust Camshaft Bank 1 Control Proportional -0.9 %

Exhaust Camshaft Bank 2 Control Proportional -0.5 %

Exhaust Camshaft Bank 2 Control Integral -46.1 %

Exhaust Camshaft Bank 1 Actuator Voltage 14.516 V

Exhaust Camshaft Bank 2 Actuator Voltage 14.430 V

Logged

Status